



TONIC II IDEALFORM BATHS

Installation Instructions

Please pass on to user



5062 02/15 **EE75415467**



Dimensions shown may vary within permitted tolerances.

Fig. 1 Panel type Α В C Max C Min D Ε F (A or C) Tonic II Rec 170x75 Α Tonic II Rec 180x80 Α Tonic II D/E 170x75 Α Tonic II D/E 180x80 Α Tonic II D-Shape 170x75 С Tonic II D-Shape180x80 С

Page 3

BEFORE YOU START

- Before commencing installation, carefully remove packaging/protective film and check for damage. If damaged, report immediately to supplier.
- Check the packs and make sure that you have all parts listed. If not, contact the supplier.
- Ensure the water feeds and waste connection points are positioned appropriately for the installation.
- Care should always be taken when drilling into walls and floors to avoid any sunken wires or pipes.
- The bath should be fully protected during the installation process.
- Please note: Although these instructions are comprehensive, it is always recommended that a technically competent installer should undertake installation.

Ref.	Description		Qty.
A	Bath Tub		1
В	Bath Legs		2
С	Centre Support Bracket		1
D	Short Bath Foot	(Jamm)	1
E	Bath Feet	(Community)	4
F	Plastic Leg Adjuster		4
G	Bath Feet Locking Nuts		10
н	No. 8 x 12 Pan Head Self Tapping Screw		4
J	No. 8 x 16 Countersunk Woodscrew		2
К	No. 8 x 20 Pan Head Self Tapping Screw		10
L	No. 8 x 30 Countersunk Woodscrew		4
М	Wall Bracket	0	2

Fig. 2

D-Shape Panel - Sold and supplied separately					
Ref.	Description	Qty.			
Р	Panel	1			
Q	Panel Clip	8			
R	Plastic Panel Clip	10			
S	No. 8 x 20 Pan Head Self Tapping Screw	16			

OR

Front Panel - Sold and supplied separately				
Ref.	Description		Qty.	
U	Panel		1	
V	Cushioning Strip		2	

End Panel - Sold and supplied separately				
Ref.	Description	Qty.		
W	Panel	1		
V	Cushioning Strip	1		

Fig. 3

INSTALLATION

1. Lay bath face down and remove legs and bags containing feet etc.

The 4 black - No. 8 x 40 long countersunk crosshead self tapping screws retaining the legs are NOT REQUIRED and should be discarded.

- Locate leg adjusters, (Ref.F) on bath frame and mark positions for the fixing screws. See
 Figure 1 for dimensions. Note: To ensure maximum panel clearance on the curve of the
 arc bath, position the leg adjuster as far away from the panel as possible. Pilot drill the
 holes (Ø3mm) in the bath frame and fix leg adjusters to frame, use screws (Ref. K).
- 3. Locate bath legs in leg adjusters ensuring that the orientation of the large leg is correct and mark positions for the fixing screws on the base board. Pilot drill the holes (Ø3mm) in the base board, to a depth of 6mm maximum. Position legs in leg adjusters and on base board and secure.


Use countersunk screws, (Ref. L) into the baseboard and pan head screws, (Ref H) into the leg adjusters.

DO NOT OVER TIGHTEN.

4. Locate centre support bracket towards the centre of the baseboard, mark screw hole positions, pilot drill holes (Ø3mm) in base board to a depth of 6mm maximum and secure bracket, use screws (Ref. J). Fit the single support leg black end cap onto relevant block (Fig. 5 & 5a) using the supplied screw.

Panel Type C only

 Fit panel clips to panel clip blocks. The panel clips (Ref. Q) must be located onto the wooden blocks with the pan head screws supplied (Ref. S), approximately 3mm forwards from the edge of the bath rim to the front of the panel clip.









- Fit the feet see Fig 5, 5a and adjust to give approximate floor to top of rim height required see Fig 1.
- 7. Turn bath over and drill for brassware if required. If the bath is to be installed with a monoblock mixer a special hole (or holes) is required to accommodate the mixer and will have to be cut by the installer in an appropriate position on the rim of a no tap hole bath to suit the bathroom layout. Full details or a template for cutting the hole (or holes) is supplied with monoblock fittings.

A template for cutting two tap holes in a no tap hole bath is supplied with the bath.

D-SHAPE INSTALLATION



ALCOVE INSTALLATION



Page 7

- 8. Fit the two wall fixing brackets (M) to bath frame as indicated in Fig. 6 and Fig. 1. Pilot drill holes (Ø3mm) in frame before fixing brackets.
- 9. Fit brassware, overflow and waste fittings.
- 10. Place bath into installation position and level bath, ensuring that the bath height is correct, (see C max in table). Note: The bath can be installed at a lower height, but this will reduce the space available for the waste to be fitted. Also, the panel(s) will need to be reduced in height by cutting a strip from the bottom edge. Reducing the panel height requires great care, therefore responsibility cannot be accepted for any errors made.
- 11. Fix bath to wall.
- 12. Fix bath to floor and ensure that all nuts are tight. Trial fit the panel(s) to verify height is correct. Note: Untrimmed panel fitment requires the height of (see C max in table). Remember to allow for floor coverings. Depending on the installation, the ends of the panel may need to be trimmed. Re-adjust if necessary.
- 13. Connect services and check for leaks.
- 14. Tile down to the height of the bath rim leaving a 3-4mm gap for waterproof sealant, see Fig. 6. An extruded sealing strip can be used for the bath to wall joint as an alternative to waterproof sealant. Protect bath during tiling.





Fig. 6

FIXING THE BATH PANEL(S)

PANEL TYPE 'C'

15. Pre fit the panel ensuring that it fits correctly. A relief on the panel ends may be required to clear skirting boards etc. Mark a line along the front of the panel on the floor. Remove panel and fix the plastic panel clips onto the floor/wall(s) (Figure 12). The front of the block at the floor should be 3mm back from the marked line. Fit the panel.




PANEL TYPE 'A'

16. Fit panel(s)

Attach the lengths of PVC cushioning strip to the top edge(s) of the panel(s) (three on the front panel and two on the end). Fit panel(s) (end panel first where appropriate) by pushing the top edge under the bath rim, Figure 13.

17. Panels can be reduced in height by cutting a strip from the bottom edge, for heights see Figure 1. Timber floor battens are not supplied but are necessary to secure the panels. Screw battens to the floor.



CARE OF BATH

This bath left our works in first class condition and the following points should be noted;

TO AVOID DISAPPOINTMENT, PLEASE REMOVE THE PROTECTIVE FILM AND INSPECT BEFORE INSTALLATION.

Responsibility will not be accepted for the installation of faulty baths.

Care of bath - for the installer:

Keep under cover in a clean, dry, weather-proof place.

Do not drop. Protect completely during and after installation (with clean felt etc.).

When making joint to waste, overflow etc. on this product, DO NOT use linseed oil putty or similar based sealing compounds. Ensure rubber washers supplied with waste fittings are located correctly to give watertight seal.

Test the fittings and then do not use the bath for any other purpose.

Please leave this leaflet for the end user to read.

WARNING

- **1. Filling.** It is advisable always to run in some cold water before turning on the hot tap.
- 2. Cleaning. The bath should always be cleaned immediately after use, preferably whilst the water is running out and the bath is still warm. The film of insoluble soap products, body fats and grime which will otherwise harden on the side of the bath is easily removed at this stage. In hard water districts insoluble lime salts are deposited below the waterline and under leaking taps. If this deposit is allowed to build up, it becomes increasingly difficult to remove and looks unsightly. Prompt cleaning is again the answer. Hot soapy water with a cloth should be used and the bath wiped dry.
- **3. Cleaners of a gritty or abrasive nature should never be used.** Worn washers on dripping taps should be replaced.
- **4. Chemicals.** Acrylic has good resistance properties to acids and alkalis but should not be allowed to come into contact with organic solvents such as dry cleaning agents and paint strippers.
- **5. Removal of scratches.** In the event of slight scratches in the bath surface a mild abrasive, similar to metal polish, can be used to polish these out.
- **6. Burning cigarettes** should not be allowed to come into contact with the surface of this bath or damage may ensue.

Product Guarantee

YEARS

Idealform Acrylic baths

Shower enclosures and bath screens

EARS

Valves and kits, bath panels taps and mixers

This covers products in domestic use by the consumer and not commercial or business use.

All Ideal Standard products must be installed, used and cared for in line with our fixing instructions, local water byelaws and current water regulations.


Access should always be left for installation, service and repair. Any relating costs are the responsibility of the owner/installer.

Guaranteed parts will be replaced if found faulty.

This guarantee does not cover general wear and tear.

Applies to the UK and Republic of Ireland only.

Proof of purchase will be required for any warranty claim.



The Bathroom Works National Avenue Kingston upon Hull HU5 4HS England Telephone: (01482) 346461 Telefax: (01482) 445886. 0870 1296085

CUSTOMER CARE FAX LINE 01482 499611 email: ukcustcare@ldealStandard.com

We pursue a policy of continuing improvement in design and performance of our products. The right is, therefore, reserved to vary specifications without notice.

Ideal Standard (UK) Ltd.

5062 02-15 **EE75415467**