








Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Pieśe de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



Position



- 1 = A 963 131 NU
- 4 = A 963 132 NU
- 8 = A 963 143 NU
- 9 = A 963 146 NU
- 10 = A 963 147 NU
- 13 = A 963 132 NU



EASY BOX
A 1000 NU







1116 / A 866 090 40
 Made in Germany



Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com





P
 Prüfdruck
 bar
 MAX. 16

	P bar		MAX. 10		5	
	T °C		MAX. 80		65	