





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu





XX = AA, AD...

- | | |
|----|--------------|
| 1 | F 960 872 XX |
| 2 | A 860 603 NU |
| 3 | B 960 473 XX |
| 4 | A 963 372 NU |
| 5 | F 960 874 XX |
| 6 | A 961 667 NU |
| 8 | A 962 715 NU |
| 9 | A 962 716 NU |
| 11 | A 962 848 NU |
| 12 | A 963 495 NU |
| 15 | A 962 385 XX |
| 16 | A 962 708 NU |
| 18 | B 960 432 NU |
| 19 | A 962 341 XX |
| 20 | A 860 162 NU |
| 21 | A 961 172 NU |
| 22 | A 961 230 XX |
| 23 | A 960 196 NU |




STRADA
A 5845 ..






0512 / A 866 539
 (+ A 865 612)
 Made in Germany



Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com





	P	bar				Q (3 bar)
	T	°C				l/min 5

